

BURNER UPGRADE REVIEW

RJM CORPORATION

Oll SS 309
petal-slaped backfloods
us donnal-slaped

SEPTEMBER 13, 1991

RMonroe

THE RECOMMENDED BURNER DESIGN MODIFICATIONS AND MATERIAL SELECTIONS ARE BEING PROVIDED BY THE RJM CORPORATION, WITH THE UNDERSTANDING THAT THE FINAL DESIGN DECISION AND IMPLEMENTATION SHALL BE THE RESPONSIBILITY OF THE INTERMOUNTAIN POWER SERVICE CORPORATION AND THE BABCOCK AND WILCOX COMPANY.

P7_003251

INTERMOUNTAIN POWER PROJECT RECOMMENDED MATERIALS

(BASED ON SLIP FIT/SEGMENTED PANEL BACK PLATE AND SLIP FIT FRONT PLATE)

\sim	N /	$\neg \land$	\IT
CO	'IV	עוע	N I

MATERIAL

REGISTER FRONT PLATE

1/2" A36 PLATE *

REGISTER BACK PLATE

1/2" TP304H PLATE *

INNER AIR SLEEVE

1/4" TP309H PLATE *

THROAT SLEEVE

1/4" TP304H PLATE *

SLIP SEAL CASING

3/16" TP304H PLATE *

COAL PIPE TIP


1/2" TP309H PLATE *


(* - DENOTES MATERIAL AS IS CURRENTLY INSTALLED)

IPP.RM


SLIP FIT REGISTER DETAIL DESIGNS

- o SLIP FIT CLIPS
- o NUMBER OF SEGMENTED BACK PLATE PANELS (ESTIMATED 4-6 REQUIRED)
- MEANS TO HOLD RADIAL AND AXIAL POSITIONS OF REGISTER
 END PLATES
- o RADIAL POSITIONING OF THROAT SLEEVE






EXISTING DESIGN (REF. 294361E-12)



PROPOSED DESIGN (REF. SK41791E-0)



EXISTING DESIGN PROBLEMS

COAL PIPE

o NOZZLE TIP BURNING/WARPING

INNER REGISTER

- o SLEEVE WARPING
- o REGISTER VANE JAMMING

OUTER REGISTER

- o BACK PLATE WARPING
- o THROAT INTERACTION WITH AIR SEAL
- o **REGISTER VANE JAMMING**

BURNER - UNIT 2

(REF. RB-0615 - NOVEMBER 24, 1988)

BURNER MODIFICATIONS

- o EXPANSION JOINTS WERE INSTALLED ON THE OUTER REGISTER DRIVE HANDLES
- o BACKPLATES AMD FRONT PLATES OF REGISTERS WERE CUT FREE AND EXPANSION CLIPS WERE INSTALLED

BURNER SETTINGS

- OUTER REGISTERS 6" (DOOR STIFFENER TO DOOR ON A PERPENDICULAR)
- o SPIN VANES 30° (WHERE 90° IS STRAIGHT THROUGH, 0° IS CLOSED)
- o BACK PLATES 5", 4", 3", 4", 5" OPEN
- o (ALL BURNER SETTINGS HAVE BEEN LOCKED IN PLACE)

BURNER UPGRADES PROPOSED MODIFICATIONS SK41791E/0

(REF. RB-614/615 - MAY 1, 1991)

OUTER AIR REGISTER

- REPLACED WITH MODIFIED HD REGISTER
- o REGISTER FRONT PLATE
 - THICKNESS FROM 1/2" TO 5/8"
 - MATERIAL FROM CARBON STEEL TO 800H
- o REGISTER BACK PLATE
 - THICKNESS FROM 1/2" TO 5/8"
 - MATERIAL FROM TP304 TO 800H
 - SUPPORT LEGS ADDED
 - CENTER SECTION ATTACHED TO FRAME WITH CLIPS (PROVIDES FOR EXPANSION)
- o REGISTER DOOR
 - THICKNESS FROM 10 GA. TO 3/16"
 - ALLOY STIFFENERS ADDED

THROAT SLEEVE

- o THICKNESS FROM 1/4" TO 3/8"
- MATERIAL FROM TP304 TO 800H
- EXPANSION RING ADDED TO OD
- o ATTACHED TO FRONT PLATE WITH CLIPS (PROVIDES FOR RADIAL EXPANSION)

BURNER UPGRADES PROPOSED MODIFICATIONS SK41791E/0

(REF. RB-614/615 - MAY 1, 1991)

(CONTINUED)

SLIP SEAL

- MOVED OUTBOARD ON FRONT PLATE TO ELIMINATE INTERFERENCE WITH EXPANSION OF THROAT SLEEVE
- SEAL REARRANGED TO MINIMIZE RADIANT HEAT ON ROPE PACKING

INNER AIR SLEEVE

- o THICKNESS FROM 1/4" TO 3/8"
- o MATERIAL FROM TP309 TO 800H
- o MATERIAL OF STIFFENERS FROM CARBON STEEL TO 800H
- o SPIN VANE DRIVE OPERATION CHANGED FROM GEARED TO PUSH/PULL
- o INNER SLEEVE LENGTH INCREASED APPROXIMATELY 10"

COAL NOZZLE


ALLOY PORTION OF TIP FROM 33" TO 48"

AERODYNAMIC ANALYSIS

IPP.A


AIR REGISTERS

- o OPERATING CONDITIONS
 - 100 PERCENT LOAD WITH 42 BURNERS
 - AIR TEMPERATURE = 650°F
 - WINDBOX TO FURNACE DIFFERENTIAL PRESSURE = 2.0 INCHES WATER
- o SETTINGS (REF. NOVEMBER 24, 1988)



OUTER REGISTER VANE EXIT FLOW ANGLE (OFF RADIAL)

IPP.AR



INNER SPIN VANE
EXIT FLOW ANGLE (OFF AXIAL)

REGISTER AERODYNAMIC SUMMARY/RESULTS

o OUTER REGISTER (PER BURNER)

incrose 55% ~ 65%

- AIR FLOW = 19.1 LBM/SECOND
- INTEGRATED SWIRL NUMBER = 1.639
- RECIRCULATION PARAMETER (AT HUB) = -0.2 INCH WATER
- o INNER REGISTER (PER BURNER)

45% -> 35%

- AIR FLOW = 15.2 LBM/SECOND


by spin vares

- INTEGRATED SWIRL NUMBER = 1.356
- RECIRCULATION PARAMETER (AT HUB) = -0.4 INCH WATER

Banconcerns Starres walthing away


INTER MOUNTAIN POWER PROJECT - UNITS 1 & 2

OUTER AIR REGISTER - EXISTING DESIGN AIR FLOW




INTER MOUNTAIN POWER PROJECT - UNITS 1 & 2

INNER AIR REGISTER - EXISTING DESIGN AIR FLOW



SWIRL NUMBER

- o MEASURE OF JET TANGENTIAL TO AXIAL MOMENTUM
- O DETERMINES SIZE OF COMBUSTION INTERNAL RECIRCULATION ZONE




Local Swirl No. =
$$\frac{rV_t}{V_x r_{tip}}$$

Integrated Swirl No. =
$$\frac{ \int_{r_{hub}}^{r_{tip}} rv_{t} (\rho V_{x} 2\pi r) dr }{ \int_{r_{hub}}^{r_{tip}} v_{x} (\rho V_{x} 2\pi r) dr }$$

IPP.SN


INTER MOUNTAIN POWER PROJECT - UNITS 1 & 2

OUTER AIR REGISTER - EXISTING DESIGN SWIRL NUMBER




INTER MOUNTAIN POWER PROJECT - UNITS 1 & 2

INNER AIR REGISTER - EXISTING DESIGN SWIRL NUMBER



RECIRCULATION PARAMETER

- MEASURE OF AXIAL MOMENTUM TO OVERCOME LOCAL STATIC
 PRESSURE TO FURNACE PRESSURE RISE
- o POTENTIAL FOR RECIRCULATION EXISTS WHEN THE PARAMETER IS A NEGATIVE VALUE




RECIRCULATION PARAMETER = [(AXIAL MOMENTUM / UNIT AREA) - PRESSURE RISE]

RECIRCULATION PARAMETER = [(
$$\rho V^2 / g_c$$
) - ($P_f - P_s$)]


INTER MOUNTAIN POWER PROJECT - UNITS 1 & 2

OUTER AIR REGISTER - EXISTING DESIGN RECIRCULATION PARAMETER




INTER MOUNTAIN POWER PROJECT - UNITS 1 & 2

INNER AIR REGISTER - EXISTING DESIGN RECIRCULATION PARAMETER



STRUCTURAL ANALYSIS

MEASURED TEMPERATURES AT FULL LOAD (AUGUST 30, 1991)




INTERMOUNTAIN POWER PROJECT HEAT TRANSFER ANALYSIS

IN SERVICE

- CONVECTIVE COOLING FROM 100 PERCENT LOAD REGISTER AIRFLOW
- o FLAME RADIATION PRIMARILY ON BACK WALL
- o BACK PLATE TEMPERATURE: 1,050°F (ANALYSIS) VS. 1,000°F AVG (THERMOCOUPLE)


OUT OF SERVICE

- o CONVECTIVE COOLING TO 20 PERCENT AIRFLOW
- RADIATION LOAD SAME AS IN SERVICE FOR WORST CASE ANALYSIS
- ACTUAL RADIATION IS LESS WITH BURNER FLAME OUT
- o PREDICTED BACK PLATE TEMPERATURE HIGHER THAN MEASURED



IP7_003275

INTERMOUNTAIN POWER PROJECT EXISTING DESIGN: IN SERVICE STRESS ANALYSIS



SUMMARY EXISTING DESIGN (REF. 294361-12) IN SERVICE

BACK PLATE

- HOT SPOT ON BACK PLATE OUTBOARD OF INNER SLEEVE WITHIN RANGE OF MEASURED TEMPERATURES
- o HIGH RADIAL TEMPERATURE GRADIENT CAUSES HIGH TANGENTIAL STRESS GRADIENT
- SEPARATION FROM SLEEVE PREDICTED WITH SUBSEQUENT CONING/BUCKLING


INNER SLEEVE

- LOW TEMPERATURE AND STRESSES EXCEPT FOR LOCAL STRESS CONCENTRATION AT BACK PLATE ATTACHMENT
- o TEMPERATURE/STRESS RELIEF WILL OCCUR FOLLOWING SEPARATION OF BACK PLATE

FRONT PLATE & THROAT SLEEVE

- LOW TEMPERATURE AND STRESSES EXCEPT FOR LOCAL STRESS CONCENTRATION AT JOINT
- o PREDICTED PEAK STRESS AT JOINT WITHIN ALLOWABLE LIMITS

IPPSUM1



IP7_003279

SUMMARY

EXISTING DESIGN (REF. 294361-12) OUT OF SERVICE

BACK PLATE

- o TEMPERATURES/STRESSES AGGRAVATED BY REDUCED COOLING AIR FLOW
- MORE SEVERE SEPARATION AND CONING/BUCKLING

INNER SLEEVE

- o MODERATE TEMPERATURES BUT STRESSES REMAIN LOW EXCEPT FOR LOCAL CONCENTRATION AT BACK PLATE ATTACHMENT
- o TEMPERATURE/STRESS RELIEF WILL OCCUR FOLLOWING SEPARATION OF BACK PLATE REDUCING LOCAL STRESS BELOW ALLOWABLE LIMITS


FRONT PLATE & THROAT SLEEVE

- o MODERATE TEMPERATURES AND STRESSES EXCEPT FOR LOCAL STRESS CONCENTRATION AT JOINT
- PREDICTED PEAK STRESS AT JOINT APPROACHING ALLOWABLE LIMIT
- o ASSUMING SOME RECIRCULATION AND HIGHER TEMPERATURE FOR THE THROAT SLEEVE, THE STRESS WILL BE OVER THE ALLOWABLE WITH EXPECTED JOINT SEPARATION

IPPSUM2

IP7_003281

PROPOSED DESIGN: IN SERVICE STRESS ANALYSIS



SUMMARY PROPOSED DESIGN (REF. SK41791E-0) IN SERVICE

BACK PLATE

- o GENERALLY SIMILAR BACK PLATE WARPING RESULTS AS IN EXISTING DESIGN
- SLIGHTLY HIGHER TEMPERATURES DUE TO GAP AT INNER SLEEVE
- o HIGHER RADIAL TEMPERATURE GRADIENT CAUSES HIGHER TANGENTIAL STRESS GRADIENT
- CONING/BUCKLING PREDICTED SIMILAR TO EXISTING DESIGN

INNER SLEEVE

LOW TEMPERATURES AND STRESSES - NO LOCAL CONCENTRATIONS


FRONT PLATE & THROAT SLEEVE

o ANALYSIS NOT PERFORMED - LOW TEMPERATURES/STRESSES EXPECTED THROUGHOUT


THROAT SLEEVE

O ANALYSIS NOT PERFORMED - STRESS IN FREE CYLINDER WILL REMAIN LOW REGARDLESS OF TEMPERATURE LEVEL

IPPSUM3



INTERMOUNTAIN POWER PROJECT PROPOSED DESIGN : OUT OF SERVICE STRESS ANALYSIS



SUMMARY PROPOSED DESIGN (REF. SK41791E-0) OUT OF SERVICE

BACK PLATE & INNER SLEEVE

o GENERALLY SIMILAR RESULTS TO "IN SERVICE", BUT HIGHER STRESSES

FRONT PLATE & THROAT SLEEVE

ANALYSIS NOT PERFORMED - SIMILAR LOW STRESS RESULTS AS "IN SERVICE"

INTERMOUNTAIN POWER PROJECT CONCLUSION AND RECOMMENDATIONS

BACK PLATE

- EXISTING DESIGN SEPARATION AND BUCKLING CAUSED BY HIGH TANGENTIAL STRESS GRADIENT
- PROPOSED DESIGN DOES NOT RELIEVE STRESS GRADIENT, SO SIMILAR SEPARATION AND BUCKLING ARE EXPECTED
- o IT IS RECOMMENDED THAT PROPOSED SLIP FIT PLATE BE DIVIDED INTO SEPARATE PANELS TO ELIMINATE TANGENTIAL STRESS GRADIENT
- SAME MATERIAL AND THICKNESS AS EXISTING DESIGN IS THEREFORE ADEQUATE


INNER SLEEVE & THROAT SLEEVE


- ACT AS FREE CYLINDERS WHEN SEPARATED FROM PLATES RESULTING IN LOW STRESSES REGARDLESS OF TEMPERATURE
- O SAME MATERIAL AND THICKNESS AS EXISTING DESIGNS ARE THEREFORE ADEQUATE


FRONT PLATE


- EXISTING DESIGN STRESS CONCENTRATION AT JOINT WITH THROAT SLEEVE ELIMINATED BY SLIP FIT PROPOSED DESIGN.
- O SAME MATERIAL AND THICKNESS AS EXISTING DESIGN IS THEREFORE ADEQUATE

MATERIAL PROPERTIES









P7_00329

INTERMOUNTAIN POWER PROJECT

- o BURNER MECHANIAL DESIGN OPTIMIZATION
- o COAL FLAME STABILIZER
- o NOx EMISSIONS